JOURNAL OF QUALITY TECHNOLOGY

Index

Volume 31, Nos. 1–4, 1999

ARTICLES

All articles, including material that appears in the Computer Programs and Technical Aids Departments, are listed alphabetically by author and numbered sequentially. These sequential article numbers are used to identify the articles in the Key Words list, which begins on page 476.

1. AGRAWAL, R.; LAWLESS, J. F.; AND MACKAY, R. J., *Analysis of Variation Transmission in Manufacturing Processes—Part II* . . . . . April, 143–154
2. AMIN, R. W. AND LEE, S. J., *The Effects of Autocorrelation and Outliers on Two-Sided Tolerance Limits* . . . . . July, 286–300
3. AMIN, R. W.; WOLFF, H.; BESENFELDER, W.; AND BAXLEY, R., JR., *EWMA Control Charts for the Smallest and Largest Observations* . . . . . April, 189–206
4. ANDERSON-COOK, C. M., *A Tutorial on One-Way Analysis of Circular-Linear Data* . . . . . January, 109–119
5. ANKENMAN, B. E., *Design of Experiments with Two- and Four-Level Factors* . . . . . October, 363–375
6. BODDEN, K. M. AND RIGDON, S. E., *A Program for Approximating the In-Control ARL for the MEWMA Chart* . . . . . January, 120–123
7. BORROR, C. M.; MONTGOMERY, D. C.; AND RUNGER, G. C., *Robustness of the EWMA Control Chart to Non-normality* . . . . . July, 309–316
8. BOX, G. E. P., *Response* . . . . . January, 067–072
9. BOX, G. E. P., *Statistics as a Catalyst to Learning by Scientific Method, Part II —A Discussion* . . . . . January, 016–029
10. BOX, G. E. P. AND LIU, P. Y. T., *Statistics as a Catalyst to Learning by Scientific Method, Part I—An Example* . . . . . January, 001–015
11. CHANG, J. T. AND FRICKER, R. D., JR., *Detecting When a Monotonically Increasing Mean Has Crossed a Threshold* . . . . . April, 217–234
12. COSTA, A. F. B., *AATS for the $\bar{X}$ Chart with Variable Parameters* . . . . . October, 455–458
13. COSTA, A. F. B., *Joint $\bar{X}$ and R Charts with Variable Sample Sizes and Sampling Intervals* . . . . . October, 387–397
14. COSTA, A. F. B., *$\bar{X}$ Charts with Variable Parameters* . . . . . October, 408–416
15. DAVIS, R. B., *Designing S-Charts with Two Average Run Length Constraints* April, 246–248
16. DOGANAKSOY, N. AND HAHN, G. J., *Discussion* . . . . . January, 047–053
17. DOWNS, B. T. AND GROUT, J. R., *An Economic Analysis of Inspection Costs for Mistake-Proofing Binomial Attributes* . . . . . October, 417–426
18. GIBBONS, D. I. AND MCDONALD, G. C., *Constrained Regression Estimates of Technology Effects on Fuel Economy* . . . . . April, 235–245
19. HONG, S. H. AND ELSAYED, E. A., *The Optimum Mean for Processes with Normally Distributed Measurement Error* . . . . . July, 338–344
20. HUNTER, J. S., *Discussion* . . . . . January, 054–057
21. JONES, L. A.; WOODALL, W. H.; AND CONERLY, M. D., *Exact Properties of Demerit Control Charts* . . . . . April, 207–216
22. KHURI, A., *Discussion* . . . . . January, 058–060
23. KITTLITZ, R. G., JR., *Transforming the Exponential for SPC Applications* . . . . . July, 301–308
24. LAWLESS, J. F.; MACKAY, R. J.; AND ROBINSON, J. A., *Analysis of Variation Transmission in Manufacturing Processes—Part I* . . . . . April, 131–142
25. LIN, D. K. J., *Discussion* . . . . . January, 061–066

26. Lu, C.-W. and Reynolds, M. R., Jr., *Control Charts for Monitoring the Mean and Variance of Autocorrelated Processes* . . . . . July, 259–274
27. Lu, C.-W. and Reynolds, M. R., Jr., *EWMA Control Charts for Monitoring the Mean of Autocorrelated Processes* . . . . . April, 166–188
28. Mason, R. L. and Young, J. C., *Improving the Sensitivity of the T^2 Statistic in Multivariate Process Control* . . . . . April, 155–165
29. Mays, D. P., *Optimal Central Composite Designs in the Presence of Dispersion Effects* . . . . . October, 398–407
30. Montgomery, D. C., *Discussion* . . . . . January, 045–046
31. Myers, R. H., *Response* . . . . . January, 073–074
32. Myers, R. H., *Response Surface Methodology—Current Status and Future Directions* . . . . . January, 030–044
33. Nelson, L. S., *The Calculation of Process Capability Indices* . . . . . April, 249–250
34. Nelson, L. S., *Contriving an Unavailable Significance Level* . . . . . July, 351–352
35. Nelson, L. S., *Notes on the Shewhart Control Chart* . . . . . January, 124–126
36. Nelson, L. S., *Some Notes on Variation* . . . . . October, 459–462
37. Park, C. and Reynolds, M. R., Jr., *Economic Design of a Variable Sampling Rate $\bar{X}$ Chart* . . . . . October, 427–443
38. Parlar, M. and Wesolowsky, G. O., *Specification Limits, Capability Indices, and Process Centering in Assembly Manufacture* . . . . . July, 317–325
39. Pfeifer, P. E., *A General Piecewise Linear Canning Problem Model* . . . . . July, 326–337
40. Polansky, A. M.; Chou, Y.-M.; and Mason, R. L., *An Algorithm for Fitting Johnson Transformations to Non-normal Data* . . . . . July, 345–350
41. Reynolds, M. R., Jr. and Stoumbos, Z. G., *A CUSUM Chart for Monitoring a Proportion When Inspecting Continuously* . . . . . January, 087–108
42. Singpurwalla, N. D., *A Probabilistic Hierarchical Classification Model for Rating Suppliers* . . . . . October, 444–454
43. Steiner, S. H., *EWMA Control Charts with Time-Varying Control Limits and Fast Initial Response* . . . . . January, 075–086
44. Tsung, F.; Shi, J.; and Wu, C. F. J., *Joint Monitoring of PID-Controlled Processes* . . . . . July, 275–285
45. Woodall, W H. and Montgomery, D C., *Research Issues and Ideas in Statistical Process Control* . . . . . October, 376–386

DEPARTMENTS

Computer Programs

6. Bodden, K. M. and Rigdon, S. E., *A Program for Approximating the In-Control ARL for the MEWMA Chart* . . . . . January, 120–123
12. Costa, A. F. B., *AATS for the $\bar{X}$ Chart with Variable Parameters* . . . . . October, 455–458
15. Davis, R. B., *Designing S-Charts with Two Average Run Length Constraints* April, 246–248
40. Polansky, A. M.; Chou, Y.-M.; and Mason, R. L., *An Algorithm for Fitting Johnson Transformations to Non-normal Data* . . . . . July, 345–350

Technical Aids

33. Nelson, L. S., *The Calculation of Process Capability Indices* . . . . . April, 249–250
34. Nelson, L. S., *Contriving an Unavailable Significance Level* . . . . . July, 351–352
35. Nelson, L. S., *Notes on the Shewhart Control Chart* . . . . . January, 124–126
36. Nelson, L. S., *Some Notes on Variation* . . . . . October, 459–462

Book Reviews

The Analysis of Variance by H. Scheffé . . . . . C. M. BORROR October, 470
Applying Generalized Linear Models by J. K. Lindsey . . . . . S. LEWIS July, 353–354
Bayesian Data Analysis by A. Gelman, J. P. Carlin, H. S. Stern, and D. B. Rubin . . . . . A. A. NEATH January, 127
Cumulative Sum Charts and Charting for Quality Improvement by D. M. Hawkins and D. H. Olwell . . . . . K. A. F. COPELAND July, 354–355
Discrete Multivariate Distributions by N. L. Johnson, S. Kotz, and N. Balakrishnan . . . . . P. R. NELSON July, 355
Engineering Statistics by D. C. Montgomery, G. C. Runger, and N. F. Hubele . . . . . R. G. HEIKES April, 251–252
Engineering Statistics: The Industrial Experience by B. Ostle, K. V. Turner, Jr., C. Hicks, and G. W. McElrath . . . . . H. BLACK-NEMBHARD April, 252–253
A First Course in Multivariate Statistics by B. Flury . . . . . K. A. F. COPELAND October, 463–464
Handbook of Statistical Methods for Engineers and Scientists by by H. M. Wadsworth, Jr. . . . . L. S. NELSON July, 355–357
Introduction to Design and Analysis of Experiments by G. W. Cobb . . . . . L. S. NELSON July, 357–358
An Introduction to Regression Graphics by D. Cook and S. Weisberg . . . . . E. S. VALEROSO January, 127–128
An Introduction to Reliability and Maintainability Engineering by C. E. Ebeling . . . . . W. ZIMMER October, 464–466
Introduction to Time Series by W. A. Fuller . . . . . C. MASTRANGELO January, 128–129
Misused Statistics by H. F. Spirer, L. Spirer, and A. J. Jaffe . . . . . L. S. NELSON October, 466
Modern Engineering Statistics by L. L. Lapin . . . . . L. S. NELSON April, 253–255
Modern Industrial Statistics by R. S. Kenett and S. Zacks . . . . . C. R. LOVELACE July, 358–359
Quality by D. C. S. Summers . . . . . D. SCHAUB January, 129–130
Randomness by D. J. Bennett . . . . . L. S. NELSON July, 359–360
Reliability for Technology, Engineering, and Management by P. Kales . . . . . S. E. RIGDON July, 360–362
The SPC Troubleshooting Guide by R. Blank . . . . . K. A. F. COPELAND January, 130
Statistical Case Studies: A Collaboration Between Academe and Industry by R. Peck, L. D. Haugh, and A. Goodman . . . . . C. M. BORROR October, 470–472
Statistical Methods by G. G. Vining . . . . . L. ZIMMER April, 255–256
Statistical Methods for Reliability Data by W. Q. Meeker and L. A. Escobar . . . . . J. B. KEATS October, 466–468
Statistical Quality Control by J. Ledolter and C. W. Burrill . . . . . L. S. NELSON October, 468–469
Statistical Tests for Mixed Linear Models by A. I. Khuri, T. Mathew, and B. K. Sinha . . . . . S. GILBERT AND R. CHRISTENSEN October, 469–470

Book Reviewers

Black-Nembhard, H. . . . . April, 252–253
Borror, C. M. . . . . October, 470
Borror, C. M. . . . . October, 470–472
Copeland, K. A. F. . . . . January, 130
Copeland, K. A. F. . . . . July, 354–355
Copeland, K. A. F . . . . . October, 463–474
Gilbert, S. and Christensen, R. . October, 469–470
Heikes, R. G. . . . . April, 251–252
Keats, J. B. . . . . October, 466–468
Lewis, S. . . . . July, 353–354
Lovelace, C. R. . . . . July, 358–359
Mastrangelo, C. . . . . January, 128–129
Neath, A. A. . . . . January, 127
Nelson, L. S. . . . . April, 253–255
Nelson, L. S. . . . . July, 355–357
Nelson, L. S. . . . . July, 357–358

Nelson, L. S. . . . . July, 359–360
Nelson, L. S. . . . . October, 466
Nelson, L. S. . . . . October, 468–469
Nelson, P. R. . . . . July, 355
Rigdon, S. E. . . . . July, 360–362
Schaub, D. . . . . January, 129–130
Valeroso, E. S. . . . . January, 127–128
Zimmer, L. S. . . . . April, 255–256
Zimmer, L. S. . . . . October, 463–464

MISCELLANEOUS

Editorial Collaborators . . . . . October, 478
Corrigenda . . . . . October, 479

KEY WORDS

The numbers listed by the key words are the identification numbers assigned to the articles as listed on the previous pages.

Adaptive Control Scheme; 12
Adjusted Average Time to Signal; 12, 13, 14
Analysis of Variance; 4
Attributes Control Charts; 21, 41
Autocorrelated Observations; 26, 27
Autocorrelated Process; 44
Autoregressive First Order Process; 2
Autoregressive Models; 1, 24
Autoregressive Moving Average Model; 26, 27
Average Run Length; 7, 15, 26, 27, 43
Bayesian Clssification Rule; 42
Bayesian Methods; 18
Bernoulli; 41
Bias; 36
Bivariate Response; 4
Canning Problem; 39
Capability Indices; 33, 38
Capability Maturity Model; 42
Cause Selecting Control Charts; 28
Central Composite Designs; 29
Change Point; 11
Chi-Squared Distribution; 15
C-Linear Association; 4
Coefficient of Variation; 36
Constrained Least Squares; 18
Control Charts; 3, 45
Correlated Data; 2
Cumulative Sum; 11, 41, 43
Cumulative Sum Control Charts; 23
Design of Experiments; 10
Demerit Rating System; 21
Directional Data; 4
D-Optimality; 29
Economic Design; 37
Economic Selection; 39
Experimental Design; 29
Experimentation; 9
Exponential Distribution; 23
Exponentially Weighted Moving Average; 11, 43
Exponentially Weighted Moving Average Control Charts; 7, 23, 26, 27
Extreme Value Control Charts; 3
Fast Initial Response; 43
First Order Autoregressive Models; 26, 27
Fractional-Factorial Designs; 5
Foldover; 5
Generalized Likelihood Ratio; 11
Generalized Linear Models; 32
Hard to Change Design Variables; 32
Heterogenous Variance; 29
Hotelling's T^2 Statistic; 28
Individuals Control Charts; 7, 23
Inspection Costs; 17
Integral Equations; 6, 26, 27
Investigation; 9, 10
I-Optimality; 29
Johnson System; 40
Markov Chain; 13, 37, 43
Measurement Error; 19
Minimum-Aberration; 5
Mistake Proofing; 17
Model Specification; 28
Monte Carlo Simulation; 11
Moment Estiamtion; 1
Multiple Responses; 32
Multivariate Control Charts; 6, 28
Nested Experiments; 3
Nonnormality; 2, 33
Nonparametric Test; 34
Normality; 33
Optimum Target Value; 19
Orthogonal Arrays; 5

Orthogonal Decomposition; 28
p-Charts; 41
Percentiles; 40
Proportion; 41
Process Capability; 33
Quality Control; 3, 12
Quality Management; 42
Quality Selection; 39
Quantiles; 40
Range; 36
Rational Subgroups; 33
Regression Analysis; 11, 18
Residuals; 26, 27, 43
Resolution; 5
Response Surface Methodology; 9, 10
Robust Designs; 32
Robustness; 9
S Control Charts; 15
Screening Experiments; 10
Scoring; 42
Shapiro-Wilk Test; 40
Shewhart Control Charts; 23, 26, 27, 33, 35
Significance Tests; 34
Stability Criteria; 33
Standard Deviation; 36
Statistical Process Control; 11, 12, 13, 14, 21, 38, 41, 44, 45
Statistical Quality Control; 45
Steepest Ascent; 10
Transformations; 33
Time Series; 44
Tolerance Limits; 2
Variable Parameters Control Charts; 12, 14
Variable Sample Size; 13, 37
Variable Sampling Intervals; 13, 37
Variance; 36
Variation Reduction; 1, 24
$\bar{X}$ Control Charts; 14